

Work Per	mit #
Work Ord	er#
Job#	Activity#

1. Work requester fills out this se		☐ Standing Work Permit			
Requester: Don Lynch	Date: 06/23/2010 Ext.: 2253		Dept/Div/Group: PO/PHENIX		
Other Contact person (if different from re	quester): Carter Biggs		Ext.: 7515		
Work Control Coordinator: Don Lynch	Start Date: 07/09/2010		Est. End Date: 10/31/2010		
Brief Description of Work: Enter MMN to	perform troubleshooting, testing a	and repair on MuTr detector sub	system and MuTrigger F		
		Equipment:		Analysisiana and MaTa Famouta	
Building: 1008	Room: IR	MuTr,MuTrigger,MMN		technicians and MuTr Experts	
2. WCC, Requester/Designee, Se	rvice Provider, and ESS&H (a	as necessary) fill out this s	section or attach analysis		
ESS&H ANALYSIS					
Radiation Concerns	None	rborne	Radiation Other		
☐ Special nuclear materials involved, n	otify Isotope Special Materials Gro	ир	☐ Fissionable materials involved, no	tify Laboratory Criticality Officer	
Radiation Generating Devices:	Radiography	Moisture Density Gauges	Soil Density Gauges	X-ray Equipment	
Safety and Security Concerns	□ None	☐ Explosives	☐ Transport of Haz/Rad Materia	al	
☐ Adding/Removing Walls or Roofs	☐ Critical Lift	☐ Fumes/Mist/Dust*	☐ Magnetic Fields*	☐ Pressurized Systems	
Asbestos*	☐ Cryogenic	☐ Heat/Cold Stress	☐ Nanomaterials/particles*	Railroad Work	
☐ Beryllium*	☐ Electrical	☐ Hydraulic	☐ Noise*	Rigging	
☐ Biohazard*	☐ Elevated Work	☐ Lasers*	☐ Non-ionizing Radiation*	Security Concerns	
Chemicals/Corrosives*	Excavation	☐ Lead*	Oxygen Deficiency*	Suspect/Counterfeit Items	
☐ Confined Space*	☐ Ergonomics*	☐ Material Handling	Penetrating Fire Walls	☐ Vacuum	
* Industrial Hygiene (IH) Review Require	_ *	material failuling	r stroughtile walls	Other	
Environmental Concerns		⊠ None	☐ Work impacts Environmental		
		Land Use Institutional	Soil		
☐ Atmospheric Discharges (rad/non-ra	d)	Controls	Activation/contamination	☐ Waste-Mixed	
☐ Chemical or Rad Material Storage or	Use	☐ Liquid Discharges	☐ Waste-Clean	☐ Waste-Radioactive	
Cesspools (UIC)		☐ Oil/PCB Management	☐ Waste-Hazardous	☐ Waste-Regulated Medical	
☐ High water/power consumption		☐ Spill potential	☐ Waste-Industrial	☐ Underground Duct/Piping	
Waste disposition by:		<u> </u>		Other	
Pollution Prevention (P2)/Waste Minim	ization Opportunity:	⊠ No □ Yes			
FACILITY CONCERNS	None None				
TAGIETT GONGERING	☐ Electrical Noise	☐ Potential to Cause a Fa	alse Alarm	Vibrations	
☐ Access/Egress Limitations	☐ Impacts Facility Use Agre	_	Temperature Change	Other	
☐ Configuration Control	☐ Maintenance Work on Vei			Other	
WORK CONTROLS	Waintenance Work on Ver	itilation dystems	Ounty interruptions		
Work Practices					
None	Exhaust Ventilation		Spill Containment	Security (see Instruction Sheet)	
☐ Notie		Posting/Warning		<u> </u>	
Back-up Person/Watch Back-up Pers	☐ HP Coverage	Signs	☐ Time Limitation	☐ Other	
□ Parriandos	□ III Cumav	☐ Scaffolding-requires	□ Marning Alarm /i.e. "high law		
Barricades	☐ IH Survey	inspection	Warning Alarm (i.e. "high leve	ei)	
Personal Protective Equipment					
□ None	☐ Ear Plugs	☐ Gloves	☐ Lab Coat	☐ Safety Glasses	
☐ Coveralls	☐ Ear Muffs	☐ Goggles	☐ Respirator*	☐ Safety Harness	
☐ Disposable Clothing	☐ Face Shield	☐ Hard Hat	☐ Shoe Covers	Safety Other	
				Shoes	
Permits Required (Permits must be valid					
None	Cutting/Welding	Impair Fire Protection S			
Concrete/Masonry Penetration	☐ Digging/Core Drilling	Rad Work Permit-RWP	No		
	☐ Electrical Working Hot	☐ Other			
Dosimetry/Monitoring					
☐ None	☐ Heat Stress Monitor	☐ Real Time Monitor	☐ TLD		
☐ Air Effluent	☐ Noise Survey/Dosimeter	Self-reading Pencil Dosimeter	☐ Waste Characterization		
Ground Water	☐ O2/Combustible Gas	Self-reading Digital Dosimeter	☑ Other Check O2 level prior to	o entry	
Liquid Effluent	☐ Passive Vapor Monitor	Sorbent Tube/Filter			
Training Requirements (List specific	training requirements)				
Training Requirements (List specific Confined Space, CA-Colider User, PHEN					
	IIX Awareness	mplexity, and coordination	If using the permit when all haz following need to sign: (Althou back of form)	ard ratings are low, only the gh allowed, there is no need to use	
Confined Space, CA-Colider User, PHEN Based on analysis above, the Walkdov	IIX Awareness	mplexity, and coordination	following need to sign: (Althou		
Confined Space, CA-Colider User, PHEN Based on analysis above, the Walkdow ratings below:	IIX Awareness vn Team determines the risk, co		following need to sign: (Althou back of form)	gh allowed, there is no need to use	
Confined Space, CA-Colider User, PHEN Based on analysis above, the Walkdov ratings below: ESS&H Risk Level:	IIX Awareness vn Team determines the risk, col	☐ High	following need to sign: (Althouback of form) WCC:	igh allowed, there is no need to use Date:	

Work Plan (procedures, timing, ed See attached procedure and data	quipment, and personnel availability sheets	need to be addresse	ed):		
Special Working Conditions Requi None	ired (e.g., Industrial Hygiene hold po	ints or other monitor	ing)		
Notifications to operations and Op	erational Limits Requirements: Non-	e			
Post Work Testing, Notification or	•				
Job Safety Analysis Required:	Yes No		Walkdown Compl	eted (Required): 🛛 🗎	Yes
Reviewed by: Primary Reviewer controlled according to BNL requir		nd risks that could im	npact ESS&H have b	een identified, a Walko	down was completed and the hazards will be
Title	Name (print)	Signature		Life #	Date
Primary Reviewer					
ES&H Professional					
Building Manager					
Service Provider					
Work Control Coordinator	Don Lynch		2	20146	
Other					
	Review Done: in series	☐ team			
Note: Signature indicates personr lob Supervisor: Vorkers:	nel performing work have read and u	nderstand the hazar	ds and permit require Contractor Superv Workers:		attachments).
Norkers are encouraged to provid	le feedback on ESS&H concerns or o	on ideas for improve	d job work flow. Use	e feedback form or space	ce below.
5. Department/Division Line	Manager or Designee				
•	work: (Permit has been reviewed, v	work controls are in r	place and site is read	dy for job.)	
Name:	Signature:		Life#:	. , ,	Date:
6. Worker provides feedbac Norker Feedback (use attached					
a) WCM/WCC: Are then	e any changes as a result of worker	feedback? Yes	☐ No		
Note: See work planning and con	trol subject area section 2.6				
. Post Job Review/Closeou	it: Work Control Coordinator (nit and ensures the work site is left in e change process to update drawings, p
Name:	Signature:		Life#:		Date:
Comments:			l		

4.1/3k11e011.doc 2 (10/2007) BNLF3093Erev4/07

MMN Entry During Shutdown for MuTr/MuTrigger North Troubleshooting

INTRODUCTION

Muon Tracker Detector (MuTr) and MuTrigger experts need to access the interior of the North Muon Magnet to troubleshoot/replace a malfunctioning cables and electronics on several of the MuTr North detector subsystems and MuTrigger electronics. Additional troubleshooting will be performed on station 1 North of the MuTr and Mu Trigger.

MMN MuTr TS&R (Troubleshoot and Repair)

The following operations will take place during the 2010 summer shutdown period

- 1. For the duration of the shutdown. all PHENIX magnets will be ramped down and locked out.
- 2. Prior to entry into the MMN C-A safety shall be contacted to sample the internal atmosphere of the MMN. When C-A safety arrives to take the, the sliding access panel shall be opened to permit sampling and an O₂ content check of the MMN internal atmosphere shall be sampled and recorded on the attached sheet.
- 3. The C-A confined space safety expert shall determine from the tests whether it is safe to enter the MMN for the purposes stated herein. *In no event shall anyone enter the MMN prior to approval of the C-A confined space monitoring expert.*
- 4. After clearance to enter has been approved, properly trained Mutr subsystem and MuTrigger FEE experts and/or properly trained PHENIX technicians shall sign the entry log sheet (attached) and may then enter and perform troubleshooting and operational checks. At any time when any personnel are inside of the MMN an additional watch person shall be stationed outside of the MMN and adjacent to the hatch to monitor the well being of those engaged in work inside. The watch person shall have no other responsibilities during his watch and may not leave his post unless relieved by an equally qualified and dedicated watch person. All those inside the MMN and the watch person shall have current BNL confined safety training and shall comply with all requirements of the BNL Confined Space SBMS standards.
- 5. During testing, HV to the MuTr detector panels may turned on and off to trouble shoot faults and test quality of the repairs. Current/voltage limits on MuTr components are within allowable working limits and/or properly shielded from personnel contact and do not require any additional permits.
- 6. After completion of the interior MMN tasks all equipment brought into the MMN shall be removed, the MMN access panel closed, and the MMN lockout removed. This work permit, the MMN entry log, and the Confined Space Entry Certification Form shall be posted near the access hatch.

7. Additional troubleshooting, maintenance and repair will be performed on various components of the MuTr and MuTrigger FEE's in station 1 north. These tasks shall all be within limits prescribed in PHENIX Awareness training for allowable electronics troubleshooting, maintenance and repair as worker planned work.



CONFINED SPACE ENTRY CERTIFICATION

Location	V 4 0000		Date	
Building 1008, IR, Muon Magnet Department	North (MMN) Divi	zian		
PO	PHE			
Building		/Location/Room:		
1008		MMN		
Supervisor/Designee	1, -		Life #	
Don Lynch/J. Carter Biggs			20146/15	5639
	PRE-ENTRY QUEST	IONS	_	
For each item, check "yes" or "no":		_	YES	NO
Is entry essential to perform work?	?			
Have all personnel been trained in	confined space entry?			
Are conditions safe to remove utili	ity-hole cover?			
Has opening been guarded?				
Is monitoring equipment calibrated	d?			
Has monitoring been performed an	nd recorded below?			
Is GFCI used, if outside or in wet	conditions?			
Is ventilation blown into bottom of	f space? (If required)			
Are personnel instructed to evacua	te upon hazard detection?			
Have all workers reviewed these en	ntry requirements?			
Radiation: If present, RWP may be	e required – review work with ESH Co	ordinator and RCD	□ Reviewed	
personnel. Evaluate hazards and c				
	SPACE CLASSIFICATION	QUESTIONS		
For each it	em, check box only if "yes"	Class 2A	Class 2B	Class 2C
Engulfment Hazard Present				
Entrapment Hazard Present				
Electrical Systems:				
 Deenergized 		X		
 Energized and Working Hot 				
• Energized, but Guarded or not	t Working Hot			
Mechanical Systems:		n/a		
 Deenergized 				
 Energized and Working Hot 				
 Energized but Guarded or not 	Working Hot			
Other Energized Systems: (e.g., ste	eam, sewage)	n/a		
 Deenergized 				
 Energized and Working Hot 				
 Energized but Guarded or not 				
	ce, based upon monitoring, but controll	able by X		
Ventilating - Monitor for O ₂ prior				
	ce, based upon monitoring, but not cont	rollable by n/a		
ventilating		,		
	space? (e.g., welding fumes, solvents)	n/a		
High Temperature/Pressure Hazard		n/a		
	checked, a Confined Space Permit IS re	-		
	ecked, and none in column 2C, a Confi	ned Space Permit IS NOT	required BUT of	continuous
monitoring and ventilating AF		1		
• If only boxes in column 2A ar	re checked, no additional requirements			
CI ACCIDIC ATTON	Classification eva	iluation		
CLASSIFICATION	I have completed the front and back of th	is Confined Space Entry Car	tification form and	classified this
class:2A	space. If the confined space is classified			
CLASS: 4A	is Class 2B, continuous monitoring and v			
		•		
	Supervisor/Designee:	Life #	Date	·
	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	L110 11	Date	•

1.0/3s02e011.doc 1 (06/2003)

BNL CONFINED SPACE ENTRY CERTIFICATION

Meter:	Serial #	Calibration Date:
Day of Use Sensor Check □ Yes □ No		
Tested By:		BNL#:

	MONITORING RESULTS				
Tested By:		BNL Number:			
	Oxygen %	Flammable Gas	Carbon Monoxide	Hydrogen Sulfide	Other:
Date/ Time	(% O2)	(% LEL)	(CO ppm)	(H2S ppm)	
Pre-Entry Certification test					
Acceptable Reading	19.5 – 23.5 %	< 10 % of LEL	<25 ppm	<10 ppm	

Supplemental sampling record

CLASS 2B CONFINED SPACE ENTRY CERTIFICATION

For Class2B spaces, continuous monitoring is required.

MONITORING RESULTS Tested By: BNL Number: Hydrogen Sulfide Oxygen % Flammable Gas Carbon Monoxide Other: Date/ Time (% O2) (% LEL) (CO ppm) (H2S ppm) Acceptable Reading 19.5 – 23.5 % < 10 % of LEL 25 ppm 10 ppm

Class 2B: Describe Method of Ventilation:		

Muon Magnet Confined Space Entry Certification Sheet

The undersigned certify that they have taken the BNL Confined Space Training, BNL Course # HP-OSH-016, within the last twenty four months, and understand the hazards involved in working in the south and north muon magnets (MMS and MMN).

DATE	SIGNATURE	LIFE/GUEST #